

Instructions


49-HASMS1

November, 2008

Separate Mounting Kit for Solid State Overloads
0.25 to 22A



ESP200 Starters
Cat No 49ASMS1




Description

The separate mounting kit allows for separate mounting of single and three phase 0.25 - 1A, 0.75 - 3.4A, 3 - 12A and 5.5 - 22A single phase ESP200 overload ranges.

Installation

Backout screws and slide separate mounting block overover-load stabs. Secure to the overload using the two captive mounting screws and torque to 5 lb.in.maximum. Insert the lineside wires into terminals in mounting block. Torque terminal screws to 11lb.in.maximum. Insert load side wires into load terminals on overload relay. Torque to 20 in.lb.maximum.

	⚠ WARNING
	Hazardous voltage. Can cause death, serious personal injury, or property damage. Disconnect power before working on this equipment.