

PA Tech Notes Volume IV Issue 1

Siemens Industry Process Analytics Tech Notes eNewsletter

May 2011

TECH NOTES

Our goal is to provide our valued customers with the latest product information, product changes, new features and technical issues resolved. By receiving this value-added product resource, you will be able to optimize your product performance.

Some of our Adobe PDF documents are password protected, please use the password: **technotes07** for those documents.

For questions or publication content suggestions, please contact [> PA Tech Notes](#).

Included in this issue of Tech Notes is the following information:

Process Gas Chromatographs (GC)

- ✓ Procedure to Clean an FID in a Working Maxum II Analyzer
- ✓ Maxum 4.3 and 5.0 Workstation: Patch
- ✓ Maxum 5.0 and MicroSAM 3.0: IP Addressing
- ✓ Maxum Workstation Windows 7 Patch 2 Upgrade

Related Links

- ✓ Process Analytics Links
- ✓ Spread the Word!

Newsletter Contact:

Jerry Wells
408 US Highway 60
Bartlesville, OK 74003

Phone: 918.662.7581

Fax: 918.662.7482

[> mailto:technotes.industry@siemens.com](mailto:technotes.industry@siemens.com)

Technical Support:

Phone: 1-800-448-8224 (U.S. Only - 24-hr)

Phone: 918-662-7030 (Outside the USA)

Fax: 918-662-7482 - Spare Parts and Technical Support

Fax: 713-939-9201 - Service and Training

[> www.usa.siemens.com/processanalytics](http://www.usa.siemens.com/processanalytics)

■ Process Gas Chromatographs (GC)

Procedure to Clean an FID in a Working Maxum II Analyzer

This procedure describes how to clean the upper body of an FID to reduce detector noise. These instructions include removal of the detector assembly, cleaning, a bake out and reinstallation procedures. [> read more](#)

Maxum 4.3 and 5.0 Workstation: Patch

Maxum Workstation Patch 5.00.03 is now available from the Siemens Process Analytics Software Download site. The patch fixes several known issues with the new software release and should be loaded on all instances of Workstation 4.3/5.0. [> read more](#)

Maxum 5.0 and MicroSAM 3.0: IP Addressing

The Maxum 5.0 and MicroSAM 3.0 software required on the newly released Syscon 2 reacts differently with regard to certain IP addressing setup procedures. These procedures include disabling the Router IP Function, Setting and Saving IP Address Changes, and DHCP Selection for IP Addresses. [> read more](#)

Maxum Workstation Windows 7 Patch 2 Upgrade

Maxum Workstation is now compatible with Windows 7 operating system. Certain Workstation operations will not function properly on the Windows 7 platform and the attached procedure outlines the necessary steps to restore proper functionality of the affected Workstation operations. [> read more](#)



■ Related Links

Process Analytics Links

- [> Tech Notes Documents Archive](#)
 - [> Newsletter Registration - Subscribe!](#)
 - [> Process Analytics Training](#)
 - [> Process Analytics Service](#)
 - [> Process Analytics Technical Library](#)
-



Spread the Word!

Please share the subscription link below with your colleagues.

To subscribe to the Siemens Process Analytics Tech Notes Newsletter, please [> click here](#).

[> SII Process Analytics Website](#)



As always, we look forward to continuously serve your Process Analytical needs, by providing you with leading products, product support and unsurpassed customer service.